


DP2 E



IT - NOTE:


Assicurarsi della perfetta coincidenza/planarità tra la base del verricello e la coperta prima di fissarla con i dadi.

Rimuovere il materiale in accesso dal foro di passaggio della catena/cima, rifinito e lisciarlo con un prodotto specifico (vernice marittima, gel o resina epossidica) assicurandosi il libero passaggio della catena/cima.

EN - NOTES:

Make sure of the perfect flatness between the winch base and the deck before fixing it with the nuts


Remove excess material from the chain passage, refine and flatten with a specialized product (marine paint, gel coat or two pack epoxy) to assure free passage for both rope and chain.



AREA DI TAGLIO
CUTTING AREA

4"

100 mm



	A	B	C	D	E	F	G	H	I
mm	Ø9	Ø108	Ø51	89	44	145	196	33.5	5
inch	Ø23/64	Ø4" 1/4	Ø2"	3" 1/2	1" 3/4	5" 47/64	7" 3/4	1"5/16	3/16

Quick

NAUTICAL EQUIPMENT
Via Flaminio, 120/A - 48124 Faenza (RA) Italy
Telefono +39-0544-413061 - Fax +39-0544-413047

Name
DRILLING TEMPLATE

Model
DP2 E

Size
A3

Rev. 2 3 4
Scale 1:1

Drawing units mm
File
Date 14/05/2019

This is an unpublished work, the copyright in which rests in Quick s.r.l. All this document and its information is supplied without liability for error or partly may be reproduced used or disclosed except as authorized by contract or permission.